

AEC 2.1 Requires Installation Reboot

June 7, 2012

Issue Severity:



High: Act immediately



Medium: Bosch Security Systems, Inc. strongly recommends you take the action(s) described below.



Low: Advisory

Product Affected:

- AEC 2.1 Controller (P/N: F01U100385)
- Kingston CF card v2.1.7.10b v1

1.0 Issue

When the AEC 2.1 controller (P/N: F01U100385) is powered up for the first time and the system has already been running continuously for a few hours, the web page might not be accessible.

2.0 Resolution

Take the following actions to prevent the issue described in 1.0:

Once the controller is powered up for the first time, and after the boot sequence is complete.

- Turn off the power on the UPS1 controller. Switch to the OFF position the power button located underneath the enclosure.
- Turn the power switch back to the ON position and allow the system to boot normally.
- Open a web browser and navigate to the UPS1 controllers IP address. The default address is 192.168.0.41.

Once logged in to the web browser, the system functions normally.



BOSCH

