Technical Bulletin **B901 Custom Functions on Access Granted**



May 19, 2015

Issue

The B901 with firmware v1.03.037 does not properly execute Access Granted-based custom functions when connected to a pre-GV4 compatible control panel (refer to *Products affected* for a list of affected control panels). If the door operation should execute a custom function on an Access Granted event, the function does not run.

This issue does not apply to B9512G/B8512G control panels or to D9412GV4/D7412GV4 v1.xx and higher control panels.

Resolution

To resolve this issue, do **one** of the following:

 Use a D9210C Access Control Module instead of a B901. Exchange B901 units for D9210C by calling (800) 366-2283.

-or-

 Update the B901 to firmware v1.03.050 when it becomes available. When available, download the firmware from the Software tab of the B901 product page on www.boschsecurity.com, and follow the instructions for updating the B901 firmware using RPS.



Bosch Security Systems, Inc.

130 Perinton Parkway

Fairport, NY 14450 USA

www.boschsecurity.com