

Technical Bulletin Inaccurate Step in RADION Life Safety Installation Manual



December 12, 2022

Issue

The RADION Life Safety Installation Manual (F.01U.361.311) contains an inaccurate statement found in Section 9.2 **Manually testing CO detectors**.

The error is found in Step 2: *Press the test button to silence the alarm and stop the test. The red light will continue to flash.*

Resolution

Step #2 is not required and should be ignored. It refers to silencing of an alarm and does not apply to testing. Pressing the button for 1 second will continue to silence the alarm.

Bosch Security Systems B.V. Torenallee 49 5617 BA Eindhoven Netherlands www.boschsecurity.com © Bosch Security Systems B.V., 2022