| From | Product Management | Telephone | Nuremberg |
|---|---|---|---|
| BT-VS | BT-VS/PAS4 | +49 911 93456 0 | 23-Jun-2021 |

# Version Note

| Product: | *BVMS on DIVAR IP* |
|---|---|
| Version: | *Listed below* |

## 1. General

The DIVAR IP products listed in this document are capable of running BVMS. Various versions have been tested and qualified in combination with distinct DIVAR IP platforms. This letter outlines details and limitations.

## 2. Patches and Installers specific for BVMS on DIVAR IP

| For BVMS version | DIP-72 | DIP-52 | DIP-71 | DIP-70 | DIP-30 | BVMS included | File |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| 11.0 | | X | | | | | DIP-52_Patch_Installer_1.0.3_for_BVMS11.0 |
| 11.0 | X | | | | | | DIP-72_Patch_Installer_1.0.3_for_BVMS11.0 |
| 11.0 | | | X | | | | DIP-71_Patch_Installer_1.0.0.005_for_BVMS11.0 |
| 10.1.1 | | X | | | | | DIP-52_Patch_Installer_1.0.2_for_BVMS10.1.1 |
| 10.1.1 | X | | | | | | DIP-72_Patch_Installer_1.0.2_for_BVMS10.1.1 |
| 10.1.1 | | | X | | | | DIP-71_Patch_Installer_1.0_for_BVMS10.1.1 |
| 10.0.1 | X | | | | | | DivarIP7000AIO_Patch_1.0 |
| 10.0.1 | | X | | | | | DIPaio5000_Patch_Installer_1.0.1 |
| 10.0 | | X | | | | | DIPaio5000_Patch_Installer_1.0.1 |
| 9.0 | X | | | | | | DivarIP7000AIO_Patch_1.0 |
| 9.0 | | X | | | | | DIPaio5000_Patch_Installer_1.0.1 |
| 9.0 | | | X | | | X | Appliance Installer 09.00.0827.0107 |
| 8.0 | | | X | X | X | X | Appliance Installer 08.00.0329 |
| 7.5 | | | X | X | X | X | Appliance Installer 07.50.432.0087 |
| 7.5 | | | X | X | X | | Patch_7.5.0.432_ImageDecoderMemory |
| 7.0 | | | X | X | X | X | Appliance Installer 07.00.223.0046 |
| 6.5 | | | X | X | X | X | Appliance Installer 6.5.0.325.0025 |
| 6.0 | | | X | X | X | X | Appliance Installer 06.00.0453 |

| From | Product Management | Telephone | Nuremberg |
|------|--------------------|-----------|-----------|
| BT-VS | BT-VS/PAS4 | +49 911 93456 0 | 23-Jun-2021 |

## 3. Tested versions

| DIVAR IP model | BVMS version earliest | BVMS version latest | notes |
|----------------|-----------------------|---------------------|-------|
| | | | |
| DIP-30 | 4.5 | 8.0 | Not in scope of new BVMS versions |
| DIP-70 | 4.5 | 8.0 | Not in scope of new BVMS versions |
| DIP-71 | 6.0 | Latest (11.0) | BVMS updates planned until Oct 2023 |
| DIP-52 | 9.0 | Latest (11.0) | BVMS updates planned until 2026 |
| DIP-72 | 9.0 | Latest (11.0) | BVMS updates planned until 2026 |
| | | | |

## 4. Notes

- The patches listed in the table can be obtained from the BVMS Appliances category in the download area: https://downloadstore.boschsecurity.com/?type=DIPBVMS

- Appliance Installer for BVMS <=9.0 installation on DIP-71 or BVMS <=8.0 installation on DIP-70 and DIP-30 can be found in the same category.

- For later versions of BVMS and newer HW generations the standard BVMS installation packages shall be used: https://downloadstore.boschsecurity.com/?type=BVMS

- BVMS upgrade on DIVAR IP shall be done by following the BVMS upgrade procedure without changing any settings in the installation wizard.

- The respective patch(es) need to be installed after BVMS upgrade on DIVAR IP to ensure proper functionality.

- Only BVMS versions, which are covered by a respective Appliance Installer or Patch, can be applied an the target platform.

- Installation instructions and additional details about the purpose and scope are included in the release notes.

- "BVMS included" means that the Appliance Installer package contains a full setup of BVMS in addition to the patches and modification, which are specific for the DIVAR IP platform.