

# Technical Bulletin

## New Generation POPIT reversed wiring

### Issue severity

- High. Act immediately
- Medium. Bosch Security Systems strongly recommends you take the action described below.
- Low. Advisory

### Products affected

Name/CTN of product

► **D9127-CHI**

### Date

August 22, 2024

### Issue

The new generation of POPIT modules will send an “Open” status when the bus wiring is reversed. Previous versions of the POPIT module would report “missing” if the bus wiring was reversed.


### Resolution

Bosch will update the new POPIT in the near future to provide the same indication of “missing” for reversed wiring in order to eliminate any potential confusion.

Old POPIT



New POPIT



**Bosch Security Systems B.V.**

Torenallee 49

5617 BA Eindhoven

Netherlands

**[www.boschsecurity.com](http://www.boschsecurity.com)**

© Bosch Security Systems B.V., 2024