




BOSCH

Access Control Interface Module

B901



en

Release Notes

Table of contents

1	Introduction	4
1.1	About documentation	4
1.2	Prerequisite	4
1.3	Requirements	4
2	Firmware version 1.05.000	6
2.1	Whats new	6
2.1.1	Door shunt time	6

1 Introduction

These release notes are for the B901 Door Controller module with firmware version 1.05.000.

1.1 About documentation

Copyright

This document is the intellectual property of Bosch Security Systems, Inc. and is protected by copyright. All rights reserved.

Bosch Security Systems, Inc. product manufacturing dates

Use the serial number located on the product label and refer to the Bosch Security Systems, Inc. website at <http://www.boschsecurity.com/datecodes/>.

Trademarks

All hardware and software product names used in this document are likely to be registered trademarks and must be treated accordingly.

1.2 Prerequisite

B901 version 1.05.000



Notice!

If upgrading from 1.03.037 or older, the B901 requires version 1.04.003 prior to upgrading to 1.05.000.

To upgrade B901 to this version (must be connected to SDI2 bus), use RPS 6.03 or higher software to install this firmware version.

New features supported within this firmware release require RPS 6.08 or higher and control panel firmware version 3.08 and higher, to be used and/or configured.

1. Save the firmware file (.fwr) to a directory to which RPS can access.
2. Import the firmware file into RPS. (Config > System > Firmware (tab) > Import (button) > .. (browse to the file directory location) > OK
3. Open the control panel account and connect the control panel.
4. Use the Firmware Update Wizard to update the B901 with the imported firmware file. Refer to RPS Help for detailed instructions.

1.3 Requirements

B901 supports the following devices.

Compatibility

Bosch Control panels	B9512G/B9512G-E B8512G/B8512G-E B6512 D9412GV4/D7412GV4 D9412GV3/D7412GV3 D9412GV2/D7412GV2 D9412G/D7412G
Bosch readers and accessories	ARD-AYH12 EM Prox Wall Mount ARD-AYJ12 EM Prox Mullion ARD-AYK12 EM Prox Mini Mullion ARD-AYQ12 EM Prox Wall Mount Vandal Resistant

	<p>ARD-AYCE65B EM Prox or PIN Mullion ARD-R10 HID iClass Mini Mullion ARD-R40 HID iClass Wall Mount D8223 HID Prox Wall Mount D8224 HID Prox Mullion D8224-SP Low-profile card reader, HIDprox D8225 HID Prox Mini Mullion D8229 PIN Reader</p>
Bosch tokens and cards	<p>ACA-ATR13 EM Tokens ACD-ATR11ISO EM Cards ACD-ATR14CS EM Clamshell Cards ACD-IC2K26-50 iClass Cards ACT-IC2K26-10 iClass Tokens D8236-10 HID Prox Cards D8236KF-10 HID Prox Tokens</p>

2 Firmware version 1.05.000

Whats new

- Door shunt time

2.1 Whats new

This section examines the new features of this firmware version.

2.1.1 Door shunt time



Notice!

In order to take advantage of the extended Door Shunt Time, control panel firmware v3.08 and higher, and RPS software v6.08 and higher are required

The longest possible selection for the door shunt time has been extended from 240 seconds to 8 hours.

Bosch Security Systems, Inc.

130 Perinton Parkway
Fairport, NY 14450
USA

www.boschsecurity.com

© Bosch Security Systems, Inc., 2019

Bosch Sicherheitssysteme GmbH

Robert-Bosch-Ring 5
85630 Grasbrunn
Germany