

Technical Bulletin

Output relays not resetting when used with powered loop devices on B/G series panels.



BOSCH

Invented for life

Issue severity

- High. Act immediately
- Medium. Bosch Security Systems strongly recommends you take the action described below.
- Low. Advisory

Products affected

- ▶ B3512, B4512, B5512, B6512, B8512G, B9512G v3.x

September 18, 2019

Issue

Output relay assigned to powered loop (D125B) or POPIT devices may not reset after alarm.

Workaround

Create a Custom Function to reset the Alarm output. Include this Custom Function in the Shortcut Menu. After Resetting Sensors activate the Custom Function to reset output and delete Event Memory.

Alternative:

Reactivate the same alarm and then reset a second time.

Second alternative:

Use CMD 54 to reset the relay/output assigned to the devices.

Bosch Security Systems B.V.

Torenallee 49

5617 BA Eindhoven

Netherlands

www.boschsecurity.com

© Bosch Security Systems B.V., 2019